



Rapid Alert System for dangerous non-food products

| | |
|--|--|
| Alert number | A12/0306/18 |
| Category | Motor vehicles |
| Risk level | Serious risk |
| Product user | Consumer |
| Product | Passenger car |
| Brand | Land Rover |
| Name | Range Rover, Discovery |
| Type / number of model | Range Rover, Range Rover Sport, Range Rover Evoque, Range Rover Velar, Discovery Sport, All-New Discovery. |
| Batch number / Barcode | Vehicles built between 05/05/2016 and 31/01/2018. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger car |
| Country of origin | United Kingdom |
| Alert submitted by | United Kingdom |
| Risk type | Fire |
| Technical defect | The brazing of the fuel rail end caps may not properly seal the fuel rail ends. |
| Risk | Over time, this can lead to a liquid fuel leak into the engine bay. |
| Measures adopted by notifying country | Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) |
| Products were found and measures were taken also in | Malta, Poland, Sweden, The Netherlands |
| Images | No pictures available |