



Rapid Alert System for dangerous non-food products

Alert number	A12/0041/18
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Pickup truck
Brand	VW
Name	Amarok
Type / number of model	Type-approval numbers: e1*2007/46*0356* e1*2007/46*0750* Type: 2H, 2HS2
Batch number / Barcode	The vehicles affected were produced between 19/12/2015 and 24/11/2017.
OECD Portal Category	77000000 - Automotive
Description	Pickup truck
Country of origin	Argentina, Germany
Alert submitted by	Germany
Risk type	Fire, Injuries
Technical defect	The servo return pipe to the steering box could be damaged by a hose clamp and/or by coming into contact with the body of the wheel housing.
Risk	A damaged pipe could leak hydraulic oil on to hot components or the brake disk, leading to the risk of a fire or an accident.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Products were found and measures were taken also in	Croatia, Denmark, Estonia, Finland, Slovenia, Sweden, The Netherlands
Images	No pictures available