

CONSUMERS

🏠 [Rapid Alert System home \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/content/pages/rapex/index_en.htm)

☰ [Back to report listings \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.listNotifications&year=2018)

🔍 [Search alerts \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=main.search)

👤 [Safe Products Online \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=SafeProductsOnline)

The Rapid Alert System for Non-Food Products (RAPEX)

Alert number: A12/0042/18

Product: Passenger car

Category: Motor vehicles

Name: Various models

Brand: Peugeot

Batch number / Barcode: 2008: manufactured between 2/10/2017 and 20/11/2017, 208: manufactured between 4/10/2017 and 27/11/2017, 3008 II: manufactured between 21/8/2017 and 26/11/2017, 308 II: manufactured between 2/10/2017 and 23/11/2017, 5008 II: manufactured between 4/10/2017 and 24/11/2017, 508: manufactured between 6/10/2017 and 23/11/2017, Partner III: manufactured between 4/10/2017 and 22/11/2017

Type / number of model: 2008 : e2*2007/46*0070*39, 208 : e2*2007/46*0070*39, 3008 II : e2*2007/46*0534*02, e2*2007/46*0534*04, 308 II e2*2007/46*0405*16, e2*2007/46*0405*17, 5008 II : e2*2007/46*0534*04, 508 : e2*2007/46*0080*34, e2*2007/46*0081*18, Partner III : e2*2001/116*0365*30, e2*2001/116*0365*31, e2*2007/46*0001*27, e2*2007/46*0001*28

Risk level: Serious

Risk type: Injuries

An engine part may not work correctly, leading to power loss.

This could potentially result in the engine stalling or engine failure. In very rare circumstances, the vehicle may unexpectedly accelerate slightly before suddenly stopping.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

Description: Passenger car

Country of origin: France

Alert submitted by: France

Products were found and measures were taken also in: Croatia, Estonia, Finland, Ireland, Malta, Poland, Slovenia, Sweden, The Netherlands

Version: 2.12.3e (2018-03-05) Disclaimer [en \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/documents/disclaimer2017_en.pdf\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/documents/disclaimer2017_en.pdf)

[fr \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/documents/disclaimer2017_fr.pdf\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/documents/disclaimer2017_fr.pdf)

[de \(https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/documents/disclaimer2017_de.pdf\)](https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/repository/documents/disclaimer2017_de.pdf)