



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0309/18
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Motorcycle
<b>Brand</b>	Honda
<b>Name</b>	GL1800A Goldwing
<b>Type / number of model</b>	Type:SC68, EU Type Approval numbers: e4*92/61*0107*06, e3*2002/24*2803*00-04
<b>Batch number / Barcode</b>	The recall affects model year 2010 – 2016 vehicles, produced from 23/09/2008 to 22/10/2015.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Motorcycle
<b>Country of origin</b>	Japan
<b>Alert submitted by</b>	Greece
<b>Risk type</b>	Injuries
<b>Technical defect</b>	The ammonium nitrate propellant used in the air bag inflator may degrade over time due to heat cycles and exposure to moisture.
<b>Risk</b>	In the event of the airbag being deployed, the excessive internal pressure may cause the inflator body to rupture and metal fragments may pass through the cushion material causing injury to the rider.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)
<b>Products were found and measures were taken also in</b>	Croatia, Estonia, Finland, Poland, Slovakia, Slovenia, Sweden, The Netherlands
<b>Images</b>	No pictures available