



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0044/18
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Hyundai
<b>Name</b>	i40
<b>Type / number of model</b>	Type-approval number: E4*2007/46*0263*12; Type: VF
<b>Batch number / Barcode</b>	The vehicles concerned were manufactured between 1/04/2011 and 26/03/2012.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	Republic of Korea
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Technical defect</b>	The clutch switch may be faulty.
<b>Risk</b>	As a consequence, if the vehicle is started when it is in gear, without the hand brake on and the clutch not engaged, the vehicle could move off when not expected causing an accident.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, Estonia, Finland, Iceland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, Sweden, The Netherlands
<b>Images</b>	No pictures available